



MOLD INSPECTION AND TESTING REPORT MOLD RELATED ILLNESS & CIRS PROGRAM

CLIENT	John Smith
PROPERTY ADDRESS	123 Sample St ~ Anytown, CA 98765
DATE OF INSPECTION	Friday, May 30, 2025

SUMMARY AND CONCLUSIONS

Based on the findings of our visual assessment and the concurrent laboratory analysis of the samples collected, the recommendation for professional mold remediation of the Kitchen and Primary Bathroom areas of the home is supported. The air sample collected in the Kitchen showed normal airborne mold spore counts as compared to our outdoor sample. However, the air sample collected at the Primary Bathroom showed elevated mold spore counts, mold growth was confirmed in both areas and water damaged building materials were present. Additional hidden mold growth is possible in all affected areas. See recommendations below.

Based on the findings of our visual assessment and the laboratory analysis of the samples collected, professional cleaning and invasive exploration of the NE Bedroom and Dining Area areas of the home is recommended. The air samples collected showed suspect airborne mold spore counts, the cavity sample collected at the Dining Area Ceiling Center of the 4 Recessed Lights showed spore types and concentrations not indicative of a mold source and water damaged building materials were present. Hidden mold growth is likely in all affected areas. See recommendations below.

Based on our visual inspection and lab samples, professional cleaning and invasive exploration of the Primary Bedroom Closet area of the home is recommended. Visible mold-like growth was observed and all building materials were present. However, the air sample collected showed the presence of Chaetomium, which can be a strong indicator of a mold source. The cavity sample collected showed high levels of contamination, and water damaged building materials were present. Hidden mold growth is likely in all affected areas. We've included invasive exploration information below.

This comprehensive MRIC inspection report demonstrates our detailed written summary & conclusions from a full investigation completed by our inspector.

Mold Inspection Sciences
Office: 800.619.6199
www.moldinspection.com

Copyright © 2025 Mold Inspection Sciences
ProjectId: 20250530_MF_JOHN

Based on the findings of our visual assessment and the laboratory analysis of the samples collected, we did not definitively detect a mold problem in the Formal Living Room, Formal Dining Room, Primary Bedroom or Living Room areas of the home. The air samples collected showed normal airborne mold spore counts as compared to our outdoor sample and the surface samples collected in the Formal Living Room, Formal Dining Room and Primary Bedroom were negative for mold growth. However, the qPCR samples collected at the Bottom Level and Top Level showed high levels of contamination, and as a result hidden mold growth is possible. Client should consider performing invasive exploration and cleaning. See recommendations below.

Based on the findings of the laboratory analysis of the samples collected, professional cleaning of the Bottom Level and Top Level areas of the home is recommended. The qPCR sample collected showed high levels of contamination. See recommendations below.

GENERAL RECOMMENDATIONS

Engage a licensed professional to evaluate and repair, as necessary, the following items related to water intrusion:

- EXTERIOR - Vegetation in contact with exterior walls and previous exterior moisture intrusion
- FORMAL LIVING ROOM - Previous leak at water supply line / previous flooding, previous water supply line, previous exterior moisture intrusion and humidity - condensation
- KITCHEN - Previous leaks and/or spills, previous humidity - condensation / previous leaks, previous sink plumbing leaks and/or spills, humidity - condensation and previous leak at water supply line

○ BATH - Previous leak at water supply line

○ HALL - Previous leak at water supply line

○ BEDROOM - Previous leak at water supply line and humidity -

○ BATH - Previous leak at water supply line and humidity -

○ CLOSET - Previous leak at water supply line

○ Previous leak at water supply line

**CONTINUED MOLD GROWTH IS POSSIBLE IF
THESE ISSUES ARE NOT CORRECTED.**

The results and recommendations based on our findings can expertly guide the best and most effective remediation procedures.

RECOMMENDATIONS FOR PROFESSIONAL MOLD REMEDIATION

All remediation activities should be performed according to the standards outlined in the IICRC S520.

Room/Area	Location within Room/Area and/or Affected Materials
Kitchen	Mold Impacted and Water Damaged Materials. Mold growth was confirmed at the Drywall and Under Island Sink. Additional hidden mold growth is possible under/around the cabinetry, within the wall cavities and/or in association with the flooring materials.
Primary Bathroom	Mold Impacted and Water Damaged Materials. The air sample collected showed elevated airborne mold spore counts and mold growth was confirmed at the Drywall. Additional hidden mold growth is possible under/around the cabinetry, within the wall cavities and/or in association with the flooring materials.

- Isolate the work area with use of containment / isolation barriers,
 - Whenever possible, a decontamination chamber should be installed at the entrance to the containment / work area,
- Establish negative air pressure within the work area by installing HEPA filtered negative air machines,
- All contents should be removed from the work area,
- Remove all water damaged and/or mold impacted non-structural materials (baseboards, trim, drywall, plaster, cabinetry, carpet, carpet pad, tack strips, underlayment, insulation, etc...),
 - During remediation, removal of affected materials (mold impacted, wet and/or previously wet materials) should continue until no visible / known impacted area wherever feasible.
- All porous building materials should be removed from the work area (window coverings, etc...),
- All exposed insulation should be removed from the work area,
- All associated debris should be double bagged and disinfected with an anti-microbial solution prior to removal from the containment area,
- All water damaged and/or mold impacted structural materials should be HEPA vacuumed, scrubbed/cleaned, damp wiped with disinfectant and then HEPA vacuumed again,
- Compressed air should be applied to all surfaces to stir up dust in space and allow for air scrubbing,

Our recommendations outline the specific types of deep cleaning required to properly address a property where a CIRS or mold-related illness patient may reside.

- If the work is occurring over several days, each day should end with a compressed air treatment.
- HEPA vacuum all surfaces within the work area,
- Damp wipe all surfaces within the work area with an appropriate surfactant,
- All exposed building materials and porous surfaces should be sealed with a *clear penetrating encapsulant,
 - ***IMPORTANT:** If colored / non-translucent encapsulant is used, full clearance will not be possible.
- All negative air machines and/or air scrubbers should be turned off,
- An appropriate non-mechanical air scrubbing solution (Such as AeroSolver), should be applied / fogged into the space,
 - Plastic sheeting should be placed on all surfaces in preparation for the application (ceiling, exposed framing, finished walls, flooring, etc...),
 - Follow the manufacturers recommendations for appropriate application, set time and recommended procedures.
 - Plastic sheeting (excluding containment/critical barriers) should be removed from surfaces, double bagged and damp wiped with an appropriate surfactant prior to removal from the containment,
- Damp wipe all surfaces within the work area with an appropriate surfactant,
- Damp wipe all surfaces within the work area with grain or isopropyl alcohol,
- Dry wipe all surfaces within the work area with appropriate electrostatic cloths.
- **IMPORTANT:** Areas must remain isolated and undisturbed until Phase I testing is performed, and the area is cleared.

RECOMMENDATIONS FOR PROFESSIONAL INVASIVE EXPLORATION

Mold growth is possible in the areas listed in the table below. Client should consider remediation by a professional or other qualified professional to perform invasive exploration. If mold growth is found, all remediation activities should be performed in accordance with the standards outlined in the IICRC S520. Proper engineering should be used to prevent the spreading of airborne mold spores during the

Our MRIC Program is designed to identify any potential mold sources, related contamination, and the proper cleaning procedures.

Location within Room/Area
When mold growth is possible within the wall cavities.
When mold growth is possible within the wall cavities or in association with the flooring materials.
After Damaged Materials. The cavity sample collected at the Ceiling Center of the 4 Recessed lights showed spore types and concentrations

	indicative of a mold source, the air sample collected showed the presence of Marker spore type molds and the qPCR sample collected showed high levels of contamination. Hidden mold growth is possible within the wall cavities and/or in association with the flooring materials.
NE Bedroom	Water Damaged Materials. The air sample collected showed suspect airborne mold spore counts. Hidden mold growth is possible within the door, within the wall cavities and/or in association with the flooring materials.
Primary Bedroom	Hidden mold growth is possible within the wall cavities and/or in association with the flooring materials.
Primary Bedroom Closet	Water Damaged Materials. The air sample collected showed the presence of Marker spore type molds and the qPCR sample collected showed high levels of contamination. Hidden mold growth is possible within the door, within the wall cavities and/or in association with the flooring materials.
Living Room	Hidden mold growth is possible within the wall cavities and/or in association with the flooring materials.

- Isolate the work area with use of containment / isolation barriers,
 - Whenever possible, a decontamination chamber should be installed at the entrance to the containment / work area,
- Establish negative air pressure within the work area by installing HEPA filtered negative air machines,
- Remove all water damaged and/or mold impacted non-structural materials (baseboards, trim, drywall, plaster, cabinetry, carpet, carpet pad, tack, underlayment, insulation, etc...),
 - During remediation, removal of affected materials (moisture, wet and/or previously wet materials) should continue until no visible / known impacted area wherever feasible.
- All exposed insulation should be removed from the work area
- All porous building materials should be removed from the work area (window coverings, etc...),
- All associated debris should be double bagged and disinfected with anti-microbial solution prior to removal from the containment area
- All water damaged and/or mold impacted structural materials should be HEPA vacuumed, scrubbed/cleaned, damp wiped with disinfectant and then HEPA vacuumed again,
- Compressed air should be applied to all surfaces to stir up dust in space and allow for air scrubbing,

This program creates a clear pathway to ensure a safe and healthy environment for CIRS patients and individuals affected by mold-related sensitivities or illnesses

- If the work is occurring over several days, each day should end with a compressed air treatment.
- HEPA vacuum all surfaces within the work area,
- Damp wipe all surfaces within the work area with an appropriate surfactant,
- All exposed building materials and porous surfaces should be sealed with a *clear penetrating encapsulant,
 - ***IMPORTANT:** If colored / non-translucent encapsulant is used, full clearance will not be possible.
- All negative air machines and/or air scrubbers should be turned off,
- An appropriate non-mechanical air scrubbing solution (Such as AeroSolver), should be applied / fogged into the space,
 - Plastic sheeting should be placed on all surfaces in preparation for the application (ceiling, exposed framing, finished walls, flooring, etc...),
 - Follow the manufacturers recommendations for appropriate application, set time and recommended procedures.
 - Plastic sheeting (excluding containment/critical barriers) should be removed from surfaces, double bagged and damp wiped with an appropriate surfactant prior to removal from the containment,
- Damp wipe all surfaces within the work area with an appropriate surfactant,
- Damp wipe all surfaces within the work area with grain or isopropyl alcohol,
- Dry wipe all surfaces within the work area with appropriate electrostatic cloths.
- **IMPORTANT:** Areas must remain isolated and undisturbed until Phase I testing is performed and the area is cleared.

RECOMMENDATIONS FOR REMOVAL OF POROUS CONTENTS & DEMOLITION RELATED TO PLANNED RENOVATIONS

During the course of demolition, it is possible that new /undiscovered water damage and/or mold growth may be discovered. Client should consider hiring a mold remediation professional or other qualified professional to perform any removal of building materials, including carpeting, related to planned renovations. If any water damage and/or mold impacted materials are discovered, Mold Remediation and/or Invasive Exploration should be performed according to the standards outlined in the IICRC S520.

Materials should be removed from the home prior to Phase 1 Clearance and should be sealed throughout the residence. In addition, if the HVAC system is to be removed, flex ducting should be removed prior to Phase 1 Clearance. All materials should follow the recommendations outlined below.

Removal should be performed with use of containment / isolation barriers,

At Mold Inspection Sciences, our MRIC Program includes the investigation of the exterior and all interior spaces in your property.

- Establish negative air pressure within the work area by installing HEPA filtered negative air machines,
- Remove all building materials necessary to accommodate for planned renovations,
- HEPA vacuum all surfaces within the work area,
- Damp wipe all surfaces within the work area with an appropriate surfactant,
- Damp wipe all surfaces within the work area with grain or isopropyl alcohol,
- Dry wipe all surfaces within the work area with appropriate electrostatic cloths.
- **IMPORTANT:** If at any time through the course of the demolition any water damage and/or mold impacted materials are discovered, Remediation and/or Invasive Exploration should be performed as outlined in the RECOMMENDATIONS FOR PROFESSIONAL MOLD REMEDIATION and/or RECOMMENDATIONS FOR PROFESSIONAL INVASIVE EXPLORATION sections above.
- **IMPORTANT:** Areas must remain isolated and undisturbed until Phase I testing is performed, and the area is cleared.

Phase I Clearance Testing (Performed 24-72 hours after work is completed)

After the mold remediation is complete, but before new building materials are installed, the remediation areas should be inspected, tested via Air and Dust Samples for Direct Analysis, and approved by Mold Inspection Sciences.

- **IMPORTANT:** Areas must remain isolated and undisturbed until Phase II testing is performed, and the area is cleared.

Phase II Clearance Testing (Performed 2-4 weeks after work is completed)

After Phase I Clearance Testing, but before new building materials are installed, the remediation areas should be inspected, tested via qPCRHM (HERTSMI) or qPCREM (ERMI) samples, and approved by Mold Inspection Sciences.

RECONSTRUCTION OF IMPACTED AREAS AND PLANNED RENOVATIONS

- Reconstruction of Impacted areas including planned renovations
 - All contractors should perform their work
 - Areas should remain contained whenever

HVAC CLEANING AND DUCT LEAKAGE SEALING

- The HVAC System should be properly cleaned
 - Establish negative air on the system with negative air machines,
 - *Entire system should be scrubbed and cleaned with appropriate scrubbing device,

This is an important aspect in determining exactly where the contamination source is and what the proper remediation procedure will be.

- ***NOTE:** When flex ducting is present, it will need to be replaced as opposed to cleaned.
- The Evaporator Coil Blower Motor and Air Handler Closet Cabinet should be properly cleaned,
 - Damp wipe all surfaces within the work area with an appropriate surfactant,
 - Damp wipe all surfaces within the work area with alcohol wipes,
 - Dry wipe all surfaces within the work area with appropriate electrostatic cloths.
- Replace the air filter,
- A temporary MERV 13 or better HVAC filter should be installed at every return air vent and supply register, and the system fan should be turned on and ran for 10 minutes.
- The temporary filters should be removed, and the return air vents, supply registers and immediate 12-24" of related ducts should be damp wiped with an appropriate surfactant followed by a dry wipe with appropriate electrostatic cloths.

Phase III Clearance Testing (Performed immediately after work is completed)
Immediately after the cleaning activities are completed, the HVAC system should be tested via Dust Samples for Direct Analysis, and approved by Mold Inspection Sciences.

- **IMPORTANT:** Immediately following the Phase III sample collection, the system should be isolated with use of containment / isolation barriers and remain so until the system is cleared.
- The HVAC System / ducts should be properly sealed from leakage,
 - AeroSeal products should be applied to ensure the system is properly functioning without leakage.
- **IMPORTANT:** Immediately following the application of the duct sealing products, the system should be isolated with use of containment / isolation barriers and remain so until the project is cleared.

We also collaborate with your healthcare provider and remediation contractor to ensure all standards are met and your concerns are fully addressed.

STEPS FOR CLEANING OF INDIRECTLY IMPACTED

Location within Room/Area
If qPCR sample showed High levels of contamination. All surfaces should be cleaned as outlined below.
If qPCR sample showed High levels of contamination. All surfaces should be cleaned as outlined below.

- Isolation / containment barriers of individual areas may be removed if needed. However, it is recommended that the structure be segmented in a reasonable manner with use of isolation / containment barriers and/or in multi-story structures segment by floors to assist in phasing of the cleaning steps and the final clearance testing.
- All porous contents should be removed from the space,
 - Porous contents should be disposed of and/or professionally cleaned.
- HEPA vacuum all surfaces within the work area,
- Plastic barriers should be removed from surfaces, double bagged and damp wiped with an appropriate anti-microbial solution prior to removal from the containment,
- An appropriate non-mechanical air scrubbing solution (Such as AeroSolver), should be applied / fogged into the space,
 - Follow the manufacturers recommendations for appropriate application, set time and recommended procedures,
- Plastic barriers should be removed from surfaces, double bagged and damp wiped with an appropriate anti-microbial solution prior to removal from the containment,
- Damp wipe all surfaces within the work area with an appropriate surfactant,
- Damp wipe all surfaces within the work area with grain or isopropyl alcohol wipes,
- Dry wipe all surfaces within the work area with appropriate electrostatic cloths.
- **IMPORTANT:** Areas must remain isolated and undisturbed until Phase IV testing is performed, and the project is cleared.

Phase IV Clearance Testing (Performed 2-4 weeks after work is completed)
After the cleaning is completed, the project should be inspected, tested via qPCRHM (HERTSMI) or qPCREM (ERMI) samples, and approved by Mold Inspection Sciences.

AIR SAMPLES

Lab Code	Location	Conclusion (Inside vs. Outside Ratio in spores/m3)	Comments
OS01	Outdoor Control Sample	Baseline	Reference
ST01	Formal Living Room	Normal Tolerances. Total spore counts (266/193)	
ST02	Formal Dining Room	Normal Tolerances. Total spore counts (133/193)	

Our inspector will gather physical data, collect photographs and provide written documentation which can be used as evidence.

ST03	Kitchen	Normal Tolerances. Total spore counts (107/193)	Recommended by inspector and approved by client
ST04	Dining Area	Suspect: Chaetomium (7/<7)	Recommended by inspector and approved by client
ST05	NE Bedroom	Suspect: Penicillium/Aspergillus (320/<7)	Recommended by inspector and approved by client
ST06	Primary Bedroom	Normal Tolerances. Total spore counts (240/193)	Recommended by inspector and approved by client
ST07	Primary Bathroom	Elevated: Chaetomium and Stachybotrys (910/7)	Recommended by inspector and approved by client
ST08	Primary Bedroom Closet	Suspect: Chaetomium (13/<7)	Recommended by inspector and approved by client
ST09	Living Room	Normal Tolerances. Total spore counts (187/193)	Recommended by inspector and approved by client

CAVITY SAMPLING

Location	Concentration (spores/m3)	Comments
Living Room	Spore counts and concentrations indicative of mold growth in the cavity: Chaetomium (53)	Recommended by inspector and approved by client

Our mold specialists take air samples, wall cavity air samples, and surface samples if needed to assess your current mold situation.*

DIRECT SURFACE SAMPLES

Lab Code	Location	Conclusion	Comments
DE01	Formal Living Room (Shutter framing)	No mold growth on our collected sample	Recommended by inspector and approved by client
DE02	Formal Dining Room (French door window trim)	No mold growth on our collected sample	Recommended by inspector and approved by client
DE03	Kitchen (Drywall)	Mold Growth: <i>Stachybotrys</i> species; <i>Ulocladium</i> species	Recommended by inspector and approved by client
DE04	Kitchen (Under Island sink)	Mold Growth: <i>Ulocladium</i> species	Recommended by inspector and approved by client
DE05	Primary Bedroom (Base of French door trim and threshold)	No mold growth on our collected sample	Recommended by inspector and approved by client
DE06	Primary Bathroom (Drywall)	Mold Growth: <i>Stachybotrys</i> species; <i>Chaetomium</i> species; <i>Ulocladium</i> species	Recommended by inspector and approved by client

*NOTE: Number and type of samples will vary depending on the observed conditions in your property at time of inspection.

QPCR-MOLD SAMPLES

Lab Code	Location	Conclusion	Comments
EM01	Outdoor Control Sample (Surfaces)	Baseline	Recommended by inspector and approved by client
EM02	Bottom Level (Surfaces)	High: <i>Aspergillus penicillioides</i> (225/ND); <i>Aspergillus versicolor</i> (188/35); <i>Chaetomium globosum</i> (360/ND); <i>Penicillium brevicompactum</i> (285/104); <i>Penicillium crustosum</i> (301/ND); <i>Scopulariopsis chartarum</i> (40/9); <i>Trichoderma atroviride</i> (69/28)	Recommended by inspector and approved by client
EM03	Top Level (Surfaces)	High: <i>Aspergillus niger</i> (116/16); <i>Aspergillus penicillioides</i> (276/ND); <i>Aspergillus versicolor</i> (127/35); <i>Chaetomium globosum</i> (77/ND); <i>Penicillium brevicompactum</i> (423/104); <i>Penicillium crustosum</i> (158/ND); <i>Penicillium spinulosum</i> (15/4); <i>Scopulariopsis chartarum</i> (1/0); <i>Stachybotrys chartarum</i> (3/0)	Recommended by inspector and approved by client

MICOTOXINS SAMPLES

Conclusion	Comments
Baseline – 126 EU/mg	Recommended by inspector and approved by client
242 EU/mg	Recommended by inspector and approved by client
1 EU/mg	Recommended by inspector and approved by client

qPCR sampling is essential to an MRIC Program investigation because it uncovers hidden environmental conditions that other methods may miss

EM02	Top Level (Surfaces)	Moderate: Dominance Index: (4.7/0.0) Prevalence Index: (37.7/0.0) WD Bacteria Burden Score: 2	Recommended by inspector and approved by client
EM03	Outdoor Control Sample (Surfaces)	Baseline Dominance Index: (0.0) Prevalence Index: (0.0) WD Bacteria Burden Score: 7	Recommended by inspector and approved by client

For additional detailed information on the sample results, please see the independent laboratory report included with this inspection report.

SAMPLE REPORT

Our qPCR samples are analyzed by our accredited laboratory so you will get 100% accurate results of the levels and types of mold contamination in your home or building


APPENDIX I

INSPECTION PHOTOS AND COMMENTS

EXTERIOR

Plants/trees are coming into contact with the roof/walls.


This condition existed multiple times. Not all occurrences are shown.



Moisture Content: **Dry**

Humidity this area: **60%**
Humidity Outdoor: **60%**

Suspected
source(s)/cause(s):
**Vegetation in contact with
exterior walls**




*Observed bushes in contact with the
exterior walls around the property.*

Our full and limited
property inspection
services include
moisture readings,
hygrometer readings,
and thermal imaging
with top-of-the-line
FLIR equipment.

EXTERIOR [SOUTH]

Firewood is stacked against the structure.



Observed some firewood against the South exterior walls.

Moisture Content: **Dry**

Humidity this area: **60%**

Humidity Outdoor: **60%**

Area Affected: **4 LF**

This technology and specialized equipment helps detect active leaks, missing insulation, and duct maintenance issues.

EXTERIOR [SOUTHEAST]

Caulking / Grout was observed in poor condition.




Moisture Content: **Dry**

Humidity this area: **60%**

Humidity Outdoor: **60%**

Area Affected: **2 SF**

Suspected
source(s)/cause(s):
**Previous exterior moisture
intrusion**




*Observed some deteriorated caulking
on this French door adjacent to the
Formal Dining Room. Also observed
some water damage to the door.*

Mold is found
outdoors and indoors.
It can enter your
home in a variety of
ways, but it thrives in
places with a lot of
moisture.

FORMAL LIVING ROOM

Area photo[s].

Humidity this area: 48%
Humidity Outdoor: 60%



Area photos of formal living space. The client stated flooded by water loss and

All areas that have been impacted by moisture will be reported, such as places where there have been leaks, flooding, around windows, or pipes.

**FORMAL LIVING ROOM
[SOUTHEAST]**

Evidence of mold-like growth was observed.




Moisture Content: **Dry**

Humidity this area: **48%**

Humidity Outdoor: **60%**

Area Affected: **4 SI**

Suspected
source(s)/cause(s):
**Previous leak at water
supply line / previous
flooding**




*Observed some mold like growth on
the window shutter framing on the
South wall to the left of the chimney.*

While some visible
signs of mold include
staining, discoloration,
and water damage,
not all indicators of
mold can be seen or
even smelled.

FORMAL DINING ROOM

Area photo[s].

Humidity this area: 51%
Humidity Outdoor: 60%



*Area photos of Formal Dining Room.
The area was impacted by a common water loss floor
mitigated.*

That's why it is critical to get in touch with a professional that has the experience and tools to detect mold beyond the surface.

FORMAL DINING ROOM [SOUTH]

Client stated a previous moisture intrusion affected this area.





Moisture Content: **Dry**

Humidity this area: **51%**

Humidity Outdoor: **60%**

Area Affected: **12 LF**

Suspected
source(s)/cause(s):
**Previous leak at water
supply line**



Observed baseboard separation from wall in this South Formal dining room wall. The client stated that some of these baseboards were reused after water flood mitigation.

Our investigations go deeper than a typical mold and moisture assessment, uncovering issues that might otherwise be missed.

FORMAL DINING ROOM [WEST]

Water damage - Moisture damage or staining observed in this area.





Moisture Content: **Dry**

Humidity this area: **51%**

Humidity Outdoor: **60%**

Area Affected: **1 SF**

Suspected
source(s)/cause(s):
**Previous exterior moisture
intrusion**




Observed water damaged floor common to the exterior of deteriorating caulking on French door.

This allows us to identify hidden contamination in enclosed spaces or areas where it may be entering from the exterior.

FORMAL DINING ROOM [WEST]

Evidence of mold-like growth was observed.



Moisture Content: **Dry**

Humidity this area: **51%**

Humidity Outdoor: **60%**

Area Affected: **2 SI**

Suspected
source(s)/cause(s):
Humidity - condensation



Observed some mold-like growth on this window of the right side French door.

Did you know? Our MRIC Program investigates historical contamination in your property providing insights into hazards you may not know were present.



KITCHEN

Area photo[s].



Humidity this area: 62%
Humidity Outdoor: 60%

* Humidity level for this area is above the ASHRAE recommended level for habitable spaces. Preferable level is between 30% and 60%.





Area photos of Kitchen. The stated in the past that this flooded by a water leak. Primary bathroom also down through kitchen fixtures.

Having a property's history is invaluable in determining the proper remediation procedures.

KITCHEN [SOUTHEAST]

Corrosion, rust, and/or leaks were observed.



Observed some rust on this light fixture under top cabinets, East wall. The client stated water was coming down through the vent hood from the common water leak from upstairs Primary Bathroom.

Moisture Content: **Dry**

Humidity this area: **62%**

Humidity Outdoor: **60%**

Area Affected: **1 SF**


Suspected source(s)/cause(s):
Previous leaks and-or spills

** Humidity level for this area is above the ASHRAE recommended level for habitable spaces. Preferable level is between 30% and 60%.*

We often find that the source of contamination is hidden and not immediately visible.

KITCHEN [NORTHEAST]

Evidence of mold-like growth was observed.



Observed mold like growth in cabinetry where the sink/dishwasher is located.

Moisture Content: **Dry**

Humidity this area: **62%**

Humidity Outdoor: **60%**

Area Affected: **2 LF**


Suspected source(s)/cause(s):
Previous humidity - condensation / Previous leaks

*** Humidity level for this area is above the ASHRAE recommended level for habitable spaces. Preferable level is between 30% and 60%.**

By combining cavity sampling with qPCR testing, we can accurately pinpoint the exact source.

KITCHEN [SOUTH]

Water damage - Moisture damage or staining observed in this area.



Observed some staining under the kitchen sink at the island.

Moisture Content: **Dry**

Humidity this area: **62%**

Humidity Outdoor: **60%**

Area Affected: **4 SF**


Suspected
source(s)/cause(s):
**Previous sink plumbing
leaks and-or spills**

*** Humidity level for this area
is above the ASHRAE
recommended level for
habitable spaces. Preferable
level is between 30% and 60%.**

qPCR sampling and testing amplifies the presence of mold spores so that not only the genus but also the species of molds present can be identified.

KITCHEN

Evidence of mold-like growth was observed.



Observed mold-like growth island sink between drain

Moisture Content: **Dry**

Humidity this area: **62%**

Humidity Outdoor: **60%**

Area Affected: **SF**




Suspected source(s)/cause(s):
Humidity - condensation

* Humidity level for this area is above the ASHRAE recommended level for habitable spaces. Preferable level is between 30% and 60%.

This deeper level of testing is useful for your health care provider in helping them determine the best course of action for your specific needs.

KITCHEN

Worn or damaged roofing materials, signs of ponding, or previous repairs were noted.



Moisture Content: **Dry**

Humidity this area: **62%**
Humidity Outdoor: **60%**

Suspected
source(s)/cause(s):
**Previous leak at water
supply line**

** Humidity level for this area
is above the ASHRAE
recommended level for
habitable spaces. Preferable
level is between 30% and 60%.*

*The client stated this kitchen area was
impacted by previous moisture
intrusion common to water leak from
upstairs Primary Bathroom.*

Since 2002, we've
performed more
than 75,000
investigations for a
variety of clients
and structures.

DINING AREA

Area photo[s].



Humidity this area: 62%
Humidity Outdoor: 60%

* Humidity level for this area is above the ASHRAE recommended level for habitable spaces. Preferable level is between 30% and 60%.



Area photos of the dining area near the kitchen. The client stated and showed me a video of water running down the recessed light fixtures from a cold water line leak from under a vanity in the Primary Bathroom.

Our testing services will determine the type of mold present in your property and provide insight into how it may be impacting your living environment

DINING AREA

Client stated a previous moisture intrusion affected this area.

This condition existed multiple times. Not all occurrences are shown.




Moisture Content: Dry

Humidity this area: 62%
Humidity Outdoor: 60%

Suspected source(s)/cause(s):
Previous leak at water supply line

* Humidity level for this area is above the ASHRAE recommended level for habitable spaces. Preferable level is between 30% and 60%.






Observed some swelling of these reused baseboards when water mitigation was done about a year ago.

When your healthcare provider recommends an expanded MRIC Program investigation, our approach may go beyond standard testing.

NE BEDROOM [NONE]

Area photo[s].

Humidity this area: 58%
Humidity Outdoor: 60%



Area photos of the NE bedroom showing previous common flooding in this room and shared room space.

This can include bacterial, endotoxin, actinomycetes, and other specialized sampling to gather the most comprehensive data about the condition of your property.

Mold

Inspection Sciences

Locations

AZ: Phoenix - Scottsdale

CA: Los Angeles • Orange County • San Diego • San Francisco • San Jose

CO: Denver • Boulder | **GA:** Atlanta | **NC:** Asheville • Charlotte • Research Triangle

OR: Portland | **SC:** Barrier Islands • Charleston • Greenville - Spartanburg

WA: Seattle • Tacoma • Vancouver



800.619.MOLD (6653)



client-service@moldsci.com

www.MoldSci.com